

Fig. 1




FIG. 2

3/17




FIG. 3




FIG. 4

5/17




FIG. 5





FIG. 6

7/17



157

8/17





FIG. 8



୬
ପିଲା

10/17




FIG. 10

11/17




FIG. 11




FIG. 12

12/17




FIG. 13




FIG. 14




FIG. 15

14/17




FIG. 16

15/17

Shape Object	<u>331</u>
Attributes	<u>380</u>
Methods	<u>382</u>
User Interface Handling	<u>388</u>
Rendering	<u>390</u>

FIG. 17

Equipment Object	<u>334</u>
Notes	<u>404</u>
Product Information	<u>408</u>
Scheduling Data	<u>406</u>
Methods	<u>402</u>
Attribute Accessing	<u>410</u>
Reporting	<u>418</u>
Data Calculating	<u>412</u>
Data Resetting	<u>414</u>
Data Updating	<u>416</u>

FIG. 18

16/17




FIG. 19




FIG. 20

17/17




FIG. 21